

Schedule and download of measured firmware release

30.05.2018

IMPORTANT NOTE: Refer to Microsoft® Security TechCenter document before clearing & resetting

TPM keys:

<https://portal.msrc.microsoft.com/en-us/security-guidance/advisory/ADV170012>

Toshiba's TPM Firmware Release Schedule:

Infineon Chipset Version: SLB 9660 TPM 1.2					
Model Name	Model Number	Affected Firmware	FW Version to Fix Issue	Target Available Date	Link to Firmware
PORTEGE WT20-B	PT15C	FW 4.40	FW 4.43	October 25th	TCJ0060700A
PORTEGE Z20t-B	PT15A	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PT15B	FW 4.40	FW 4.43	October 25th	TCJ0060700A
PORTEGE Z30-B	PT251	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PT253	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PT254	FW 4.40	FW 4.43	October 25th	TCJ0060700A
PORTEGE Z30-C	PT261	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PT263	FW 4.40	FW 4.43	October 25th	TCJ0060700A
Satellite Pro A50-C	PS56A	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS56C	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS56J	FW 4.40	FW 4.43	October 25th	TCJ0060700A
Satellite Pro R50-B	PSSG2	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PSSG3	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PSSG7	FW 4.40	FW 4.43	October 25th	TCJ0060700A
Satellite Pro R50-C	PS562	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS566	FW 4.40	FW 4.43	October 25th	TCJ0060700A
TECRA A50-C	PS569	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS56D	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS56H	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS56M	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS57B	FW 4.40	FW 4.43	October 25th	TCJ0060700A
TECRA C50-B	PSSG3	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PSSG6	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PSSG7	FW 4.40	FW 4.43	October 25th	TCJ0060700A
TECRA C50-C	PS561	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS563	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PS565	FW 4.40	FW 4.43	October 25th	TCJ0060700A
TECRA Z40-B	PT454	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PT459	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PT45F	FW 4.40	FW 4.43	October 25th	TCJ0060700A
	PT45G	FW 4.40	FW 4.43	October 25th	TCJ0060700A
TECRA Z40-C	PT463	FW 4.40	FW 4.43	October 25th	TCJ0060700A

Infineon Chipset Version: SLB 9665 TPM 2.0					
Model Name	Model Number	Affected Firmware	FW Version to Fix Issue	Target Available Date	Link to Firmware
PORTEGE A30T-C	PT361	FW 5.50	FW 5.62	November 9th	TCH0416800G
PORTEGE R30-C	PT363	FW 5.50	FW 5.62	November 9th	TCH0416800G
	PT365	FW 5.50	FW 5.62	November 9th	TCH0416800G
PORTEGE Z30-C	PT261	FW 5.50	FW 5.62	November 9th	TCH0416800G
	PT263	FW 5.50	FW 5.62	November 9th	TCH0416800G
	PT265	FW 5.50	FW 5.62	November 9th	TCH0416800G
TECRA A40-C	PS463	FW 5.50	FW 5.62	November 9th	TCH0416800G
TECRA C40-C	PS461	FW 5.50	FW 5.62	November 9th	TCH0416800G
	PS462	FW 5.50	FW 5.62	November 9th	TCH0416800G
	PS465	FW 5.50	FW 5.62	November 9th	TCH0416800G
TECRA Z40-C	PT461	FW 5.50	FW 5.62	November 9th	TCH0416800G
	PT463	FW 5.50	FW 5.62	November 9th	TCH0416800G
	PT465	FW 5.50	FW 5.62	November 9th	TCH0416800G
PORTEGE R30-C	PT361	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PT363	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PT365	FW 5.51	FW 5.62	November 9th	TCH0416800G
PORTEGE X20W-D	PRT12	FW 5.51	FW 5.62	November 9th	TCH0416800G

PORTEGE Z30-C	PT261	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PT263	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PT265	FW 5.51	FW 5.62	November 9th	TCH0416800G
Satellite Pro A50-C	PS575	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS57D	FW 5.51	FW 5.62	November 9th	TCH0416800G
Satellite Pro R50-C	PS572	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS573	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS576	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS57E	FW 5.51	FW 5.62	November 9th	TCH0416800G
TECRA A40-C	PS463	FW 5.51	FW 5.62	November 9th	TCH0416800G
TECRA A50-C	PS579	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS57B	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS57H	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PT571	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PT573	FW 5.51	FW 5.62	November 9th	TCH0416800G
TECRA C40-C	PS461	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS462	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS465	FW 5.51	FW 5.62	November 9th	TCH0416800G
TECRA C50-C	PS571	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS572	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS576	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PS57E	FW 5.51	FW 5.62	November 9th	TCH0416800G
TECRA Z40-C	PT461	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PT463	FW 5.51	FW 5.62	November 9th	TCH0416800G
	PT465	FW 5.51	FW 5.62	November 9th	TCH0416800G
TECRA Z50-C	PT577	FW 5.51	FW 5.62	November 9th	TCH0416800G
PORTEGE A30-D	PT381	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PT382	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PT383	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PT385	FW 5.61	FW 5.62	November 9th	TCH0416800G
PORTEGE X20W-D	PRT12	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PRT13	FW 5.61	FW 5.62	November 9th	TCH0416800G
PORTEGE X30-D	PT272	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PT274	FW 5.61	FW 5.62	November 9th	TCH0416800G
Satellite Pro A50-D	PS585	FW 5.61	FW 5.62	November 9th	TCH0416800G
Satellite Pro R50-D	PS582	FW 5.61	FW 5.62	November 9th	TCH0416800G
TECRA A50-D	PS586	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PS589	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PS58A	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PS58B	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PT583	FW 5.61	FW 5.62	November 9th	TCH0416800G
TECRA C40-D	PS481	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PS482	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PS483	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PS485	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PS486	FW 5.61	FW 5.62	November 9th	TCH0416800G
TECRA C50-D	PS581	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PS582	FW 5.61	FW 5.62	November 9th	TCH0416800G
TECRA X40-D	PT472	FW 5.61	FW 5.62	November 9th	TCH0416800G
	PT474	FW 5.61	FW 5.62	November 9th	TCH0416800G
TECRA Z50-D	PT581	FW 5.61	FW 5.62	November 9th	TCH0416800G

Infineon Chipset Version: SLB 9665 TPM 2.0					
Model Name	Model Number	Affected Firmware	FW Version to Fix Issue	Target Available Date	Link to Firmware
PORTEGE Z20t-C	PT16A	FW 5.50	FW 5.62	November 15th	TCH0416800G
	PT16B	FW 5.50	FW 5.62	November 15th	TCH0416800G
PORTEGE WT20-C	PT16C	FW 5.51	FW 5.62	November 15th	TCH0416800G
PORTEGE Z20t-C	PT16A	FW 5.51	FW 5.62	November 15th	TCH0416800G
	PT16B	FW 5.51	FW 5.62	November 15th	TCH0416800G

Infineon Chipset Version: SLB 9665 TPM 2.0					
Model Name	Model Number	Affected Firmware	FW Version to Fix Issue	Target Available Date	Link to Firmware
Toshiba dynaEdge	POC11	FW 5.61	FW 5.62	November 29th	TCH0416800G

Infineon Chipset Version: SLB 9655 TPM 1.2					
Model Name	Model Number	Affected Firmware	FW Version to Fix Issue	Target Available Date	Link to Firmware
PORTEGE R30-A	PT341	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT343	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT344	FW 4.32	FW 4.34	March 2018	TCJ0064100A
PORTEGE Z10t-A	PT141	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT142	FW 4.32	FW 4.34	March 2018	TCJ0064100A
PORTEGE Z30-A	PT241	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT243	FW 4.32	FW 4.34	March 2018	TCJ0064100A
PORTEGE Z30t-A	PT24A	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT24C	FW 4.32	FW 4.34	March 2018	TCJ0064100A
Satellite Pro A50-A	PT64N	FW 4.32	FW 4.34	March 2018	TCJ0064100A
Satellite Pro R50-B	PSSG0	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PSSG1	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PSSG4	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PSSG5	FW 4.32	FW 4.34	March 2018	TCJ0064100A
TECRA A50-A	PT641	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT644	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT645	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT648	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT64Q	FW 4.32	FW 4.34	March 2018	TCJ0064100A
TECRA C50-B	PSSG1	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PSSG4	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PSSG5	FW 4.32	FW 4.34	March 2018	TCJ0064100A
TECRA W50-A	PT640	FW 4.32	FW 4.34	March 2018	TCJ0064100A
TECRA Z40-A	PT444	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT449	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT44F	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT44G	FW 4.32	FW 4.34	March 2018	TCJ0064100A
TECRA Z50-A	PT540	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT544	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT545	FW 4.32	FW 4.34	March 2018	TCJ0064100A
WT310	PT143	FW 4.32	FW 4.34	March 2018	TCJ0064100A
	PT144	FW 4.32	FW 4.34	March 2018	TCJ0064100A

* The information in this document is subject to change without notice.

* "Infineon" is a trademark of Infineon Technologies in the U.S. and other countries.

* "Microsoft" is a trademark of Intel Microsoft, Inc. in the U.S. and other countries.

* Other names and brands may be claimed as the property of others.